

MS4 Annual Report/Interim Progress Certification—2025

version 1.0

(Submission #: HQA-NSAW-A6CZE, version 1)

Details

Submission Alias MS4 Annual Report/Interim Progress Certification—2025_NC
Originally Started By Danielle Cinguina
Alternate Identifier NYR20A044
Submission ID HQA-NSAW-A6CZE
Status Draft

Form Input

MS4 Operator Information

Municipality Name or Legal Entity Name
Town of North Castle

Permit ID #:
NYR20A044

MS4 Operator Type
Traditional land use control

Traditional Land Use Control
Town

Traditional Land Use Control

Traditional land use control MS4 Operator requirements are found in Part VI of the MS4 General Permit.

Legal Municipal/Entity Mailing address

15 Bedford Road
Armonk, NY 10504
Westchester

Ranking Official

Official Title	First and Last Name	Phone	Email
Town Supervisor	Joseph Rende	914-273-3000	jrende@northcastleny.com

Report Preparer

Report Preparer Title	First and Last Name	Phone	Email
Contract Engineer	Joseph Cermele	914-273-2323	jcermele@kscjconsulting.com

Stormwater Program Coordinator

Coordinator Title	First and Last Name	Phone	Email
Stormwater Program Coordinator	Robert Melillo	914-273-3000	rmelillo@northcastleny.com

Part IV**Was the information in this section completed as part of a coalition/group?**

No

MS4 General Permit Resources

Use the following webpages for more information on the permit and fact sheet:

[MS4 Permit Webpage](#)[MS4 Toolbox](#)**SWMP Plan****Annually: Have the alternative implementation agreements in the SWMP Plan been updated? (Part IV.A.1.e.)**

Yes

Annually: Has the SWMP been updated? (Part IV.B.3.)

No

Please clarify the reason for selecting "No" for this item.

The Town's SWMP is in the process of being updated.

Mapping

Annually: Has the comprehensive system mapping been updated? (Part IV.D.)

Yes

What tools are used to satisfy the comprehensive system mapping requirements? (e.g. paper maps, GIS, web mappers, etc.)

GIS mapping

Within three (3) years of the EDC: Has Phase I of the comprehensive mapping been completed? (Part IV.D.2.a.)

No

Please clarify the reason for selecting "No" for this item.

Phase I of the comprehensive mapping will be completed by Year 3

Within five (5) years of the EDC: Has Phase II of the comprehensive mapping been completed? (Part IV.D.2.b.)

No

Please clarify the reason for selecting "No" for this item.

Phase II of the comprehensive mapping will be completed by Year 5

Legal Authority

Within three (3) years of the EDC: For newly designated MS4 Operators, has adequate legal authority been developed and implemented? (Part IV.E.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

The Town is not a newly designated MS4 Operator

Please enter any comments related to the questions in this section below:

NONE PROVIDED

Part V

In Year 5: Has the SWMP Plan been evaluated? (Part V.C.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

The SWMP Plan will be evaluated in Year 5

Part VI

Which MCMs in this Part were completed as a coalition/group, if any?

NONE PROVIDED

Minimum Control Measure 1

Within three (3) years of the EDC: Have the focus areas been identified? (Part VI.A.1.a.)

Yes

What focus areas were identified?

Areas discharging to waters with Class AA-S, A-S, AA, A, B, SA, or SB waters (mapped in accordance with Part IV.D.1.e.ii.a))

TMDL watersheds listed in Table 3 (subject to Part IX. requirements; mapped in accordance with Part IV.D.1.e.ii.c))

Areas with on-site wastewater systems (subject to Part VIII. or Part IX. requirements)

Sewersheds for impaired waters listed in Appendix C (subject to Part VIII. requirements; mapped in accordance with Part IV.D.1.c. for MS4 Operators continuing coverage and Part IV.D.2.a.ii. for newly designated MS4 Operators)

Areas with construction activities

Residential, commercial, and industrial areas (mapped in accordance with Part IV.D.1.e.iii.)

Areas with illicit discharges

Within three (3) years of the EDC: Have the target audience(s) and associated pollutant generating activities been identified? (Part VI.A.1.b.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 3

Within three (3) years of the EDC: Have the education and outreach topics been identified and how the education and outreach topics will reduce the potential for pollutants explained? (Part VI.A.1.c.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 3

In Year 5: Has the method(s) used for distribution of educational messages been identified? (Part VI.A.2.a.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

In Year 5: Has one educational message been delivered to each target audience(s) for each focus area based on the education and outreach topic(s)? (Part VI.A.2.b.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

In Year 4 and Year 5: Have target audiences, focus areas, and/or education and outreach topics been updated? (Part VI.A.2.c.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 4 and 5

Please enter any comments related to the questions in this section below:

The town continues to update their webpage for stormwater management to include listings of available education materials, notices of upcoming regional presentations and related stormwater management events, print and make available brochures and newspaper printings on targeted management practices and continues to develop a collection of educational stormwater management materials to make available to the public.

Minimum Control Measure 2

Annually: Has an opportunity for public involvement/participation in the development and implementation of the SWMP been provided? (Part VI.B.1.a.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

The SWMP is in the process of being developed by the Town and public involvement will be solicited.

Annually: Has the public been informed about the opportunity for their involvement in the development and implementation of the SWMP and how they can get involved? (Part VI.B.1.b.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

The SWMP is in the process of being developed by the Town and public involvement will be solicited.

Annually: Has an opportunity to review and comment on the publicly available SWMP Plan been provided? (Part VI.B.2.a.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

The SWMP is in the process of being developed by the Town and public involvement will be solicited.

Annually: Has an opportunity to review and comment on the draft annual report been provided? (Part VI.B.2.b.i.)

Yes

What opportunity for review and comment on the draft annual report has been provided?

Posting of draft Annual Report on a public website

Annually: Have the comments received on the SWMP Plan been summarized? (Part VI.B.2.c.i.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

No comments have been received

Annually: Have the comments received on the draft annual report been summarized? (Part VI.B.2.c.i.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

No comments have been received

Please enter any comments related to the questions in this section below:

The Town continues participation as a member of EOHWC, provides public notice through televised Town Board meetings and the town website, provides full access to the public to be able to review and request copies of all information collected and developed as part of the town SWMP. The town posts the annual report on the website for review and comment by the public with notice of availability made at a public Town Board meeting.

Minimum Control Measure 3

Within three (3) years of the EDC: Has an inventory of monitoring locations been developed? (Part VI.C.1.c.i.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 3

In Year 4 and Year 5: Has the monitoring location inventory been updated? (Part VI.C.1.c.ii.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 4 and 5

Within three (3) years of the EDC: Have monitoring locations been prioritized? (Part VI.C.1.d.i.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 3

In Year 4 and Year 5: Has the monitoring location prioritization been updated? (Part VI.C.1.d.iii.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 4 and 5

Within two (2) years of the EDC: Has a monitoring locations inspection and sampling program been developed and implemented? (Part VI.C.1.e.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 2

In Year 5: Have all the monitoring locations been inspected? (Part VI.C.1.e.i.a))
N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Year 5

In Year 5: Has training on the MS4 Operator's monitoring locations inspection and sampling procedures been provided? (Part VI.C.1.e.ii.)
N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Year 5

In Year 3, Year 4, and Year 5: Have the names, titles, and contact information for the individuals who have received monitoring locations inspection and sampling training been updated? (Part VI.C.1.e.iii.)
N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Years 3, 4 and 5

In Year 3, Year 4, and Year 5: Have the monitoring locations inspection and sampling procedures been updated? (Part VI.C.1.e.iv.)
N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Years 3, 4 and 5

Within two (2) years of the EDC: Has an illicit discharge track down program been developed and implemented? (Part VI.C.2.)
Yes

In Year 5: Has training on the MS4 Operator's illicit discharge track down procedures prior to conducting illicit discharge track down been provided? (Part VI.C.2.b.)
N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Year 5

In Year 3, Year 4, and Year 5: Have the names, titles, and contact information for the individuals who have received illicit discharge track down procedures training been updated? (Part VI.C.2.c.)
N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Years 3, 4 and 5

In Year 3, Year 4, and Year 5: Have the illicit discharge track down procedures been reviewed and updated? (Part VI.C.2.d.)
N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 3, 4 and 5

Within two (2) years of the EDC: Has an illicit discharge elimination program been developed and implemented? (Part VI.C.3.)

Yes

In Year 5: Has training on the MS4 Operator's illicit discharge elimination procedures prior to conducting illicit discharge elimination been provided? (Part VI.C.3.b.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

In Year 3, Year 4, and Year 5: Have the names, titles, and contact information for the individuals who have received illicit discharge elimination procedures training been updated? (Part VI.C.3.c.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 3, 4 and 5

In Year 3, Year 4, and Year 5: Have the illicit discharge elimination procedures been reviewed and updated? (Part VI.C.3.d.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 3, 4 and 5

Please enter any comments related to the questions in this section below:

Approximately 20% (166 actual inspected) of the total number of stormwater outfalls (447) are required to be inspected annually by the Town Consulting Engineer. Outfall reconnaissance reports are provided to the Town Highway Dept for their records, identifying those outfalls that may require repair.

The Town Building Department and Highway Department, identify, monitor and order remedy/elimination of any illicit discharges that may be detected. There were no illicit discharges detected in this reporting period.

Minimum Control Measure 4

Within one (1) year of the EDC: Has a construction oversight program been developed and implemented? (Part VI.D.3)

Yes

In Year 5: Has training on the MS4 Operator's construction oversight procedures prior to conducting construction oversight been provided? (Part VI.D.3.b.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

In Year 2, Year 3, Year 4, and Year 5: Have the names, titles, and contact information for the individuals who have received construction oversight procedures training been updated? (Part VI.D.3.c.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 2, 3, 4 and 5

In Year 2, Year 3, Year 4, and Year 5: Have the construction oversight procedures been reviewed and updated? (Part VI.D.3.e.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 2, 3, 4 and 5

Annually: Has the inventory of construction sites been updated? (Part VI.D.4.b.)

Yes

How many construction sites are on the inventory?

36

Within one (1) year of the EDC: Have construction sites been prioritized? (Part VI.D.5.a.)

Yes

How many high priority construction sites are on the inventory?

6

In Year 2, Year 3, Year 4, and Year 5: Has the construction site prioritization been updated? (Part VI.D.5.c.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 2, 3, 4 and 5

Within three (3) years of the EDC: Have the individuals responsible for reviewing SWPPPs for acceptance received four (4) hours of Department endorsed training in proper erosion and sediment control principles from a Soil & Water Conservation District, or other Department endorsed entity prior to conducting SWPPP reviews and/or approvals? (Part VI.D.6.a.i.)

Yes

Annually: Have the names, titles, and contact information for the individuals who have received four (4) hours of Department endorsed training in proper erosion and sediment control principles from a Soil & Water Conservation District, or other Department endorsed entity, for individuals responsible for reviewing SWPPPs been updated? (Part VI.D.6.d.)

Yes

Are pre-construction meetings conducted prior to the commencement of construction activity? (Part VI.D.7.)

Yes

Within three (3) years of the EDC: Have the individuals responsible for construction site inspections received four (4) hours of Department endorsed training in proper erosion and sediment control principles from a Soil & Water Conservation District, or other Department endorsed entity prior to conducting construction site inspections? (Part VI.D.8.a.i.)

Yes

Annually: Have all sites with construction activity identified in the inventory been inspected during active construction after the pre-construction meeting, or sooner if deficiencies are noted that require attention? (Part VI.D.8.c.)

Yes

Annually: Have the names, titles, and contact information for the individuals who have received four (4) hours of Department endorsed training in proper erosion and sediment control principles from a Soil & Water Conservation District, or other Department endorsed entity, for individuals responsible for construction site inspections been updated? (Part VI.D.8.d.)

Yes

Are final construction site inspections conducted? (Part VI.D.9.)

Yes

Please enter any comments related to the questions in this section below:

All SWPPPs are reviewed by the Town Consulting Engineer for compliance with the CGP and Stormwater Design Manual. All construction sites are inspected by the Town Consulting Engineer. The Town continues to enforce the stormwater ordinance which reflects updates to the CGP as well as implements a local code requirement for developers to design a SWPPP for disturbance >5,000 sf for projects town-wide regardless of the site's location in the watershed.

Minimum Control Measure 5

Annually: Has the inventory of post-construction SMPs been updated? (Part VI.E.2.c.)

Yes

How many post-construction SMPs are on the inventory?

27

Within five (5) years of the EDC: Have the required components been included in the post-construction SMP inventory? (Part VI.E.2.d.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

Within one (1) year of the EDC: Has a post-construction SMP inspection and maintenance program been developed and implemented? (Part VI.E.4.)

Yes

Has each post-construction SMP identified in the inventory been inspected at the required frequency? (Part VI.E.4.a.)

Yes

In Year 5: Has training on the MS4 Operator's post-construction SMP inspection and maintenance procedures prior to conducting post-construction SMP inspection and maintenance been provided? (Part VI.E.4.b.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

Annually: Have names, titles, and contact information for the individuals who have received post-construction SMP inspection and maintenance procedures training updated? (Part VI.E.4.c.)

No

Please clarify the reason for selecting "No" or "N/A" for this item.

The Town has not had training in this reporting period.

In Year 2, Year 3, Year 4, and Year 5: Have the post-construction SMP inspection and maintenance procedures been reviewed and updated? (Part VI.E.4.d.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 2, 3, 4 and 5

Please enter any comments related to the questions in this section below:

The town continues to work with the EOHWC to identify and implement stormwater retrofit projects as part of their "bubble compliance".

Minimum Control Measure 6

Within three (3) years of the EDC: Have best management practices (BMPs) been incorporated into the municipal facility program and municipal operations program? (Part VI.F.1.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 3

Within three (3) years of the EDC: Has a municipal facility program been developed and implemented? (Part VI.F.2.a.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 3

In Year 5: Has training on the MS4 Operator's municipal facility procedures prior to conducting municipal facility procedures been provided? (Part VI.F.2.a.ii.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Year 5

In Year 4 and Year 5: Have the names, titles, and contact information for the individuals who have received municipal facility procedures training been updated? (Part VI.F.2.a.iii.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Years 4 and 5

In Year 4 and Year 5: Have the municipal facility procedures been updated? (Part VI.F.2.a.iv.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Years 4 and 5

Within two (2) years of the EDC: Has a municipal facility inventory been developed? (Part VI.F.2.b.i.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Year 2

In Year 3, Year 4, and Year 5: Has the municipal facility inventory been updated? (Part VI.F.2.b.ii.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Years 3, 4 and 5

Within three (3) years of the EDC: Have the municipal facilities been prioritized? (Part VI.F.2.c.i.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Year 3

In Year 4 and Year 5: Has the municipal facility prioritization been updated? (Part VI.F.2.c.iii.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Years 4 and 5

Within five (5) years of the EDC: Has a municipal facility specific SWPPP for each high priority municipal facility been developed? (Part VI.F.2.d.i.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Year 5

In Year 5: Has all wet weather visual monitoring of the monitoring locations at all high priority municipal facilities been conducted? (Part VI.F.2.d.ii.a))

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

In Year 5: Has a comprehensive site assessment for each high priority municipal facility been completed? (Part VI.F.2.d.ii.c))

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

In Year 5: Has a comprehensive site assessment for each low priority municipal facility been completed? (Part VI.F.2.e.ii.c))

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

Within three (3) years of the EDC: Has a municipal operations program been developed? (Part VI.F.3.a.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 3

In Year 5: Has training on the MS4 Operator's municipal operations procedures prior to conducting municipal operations been provided? (Part VI.F.3.a.ii.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

In Year 4 and Year 5: Have the names, titles, and contact information for the individuals who have received municipal operations procedures training been updated? (Part VI.F.3.a.iii.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 4 and 5

In Year 4 and Year 5: Have the municipal operations procedures been reviewed and updated? (Part VI.F.3.a.iv.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 4 and 5

Within three (3) years of the EDC: Have catch basins in need of inspection been identified? (Part VI.F.3.c.i.)

Yes

Within three (3) years of the EDC: Has catch basin inspection information been inventoried? (Part VI.F.3.c.ii.)

Yes

How many catch basins have been inspected?

1239

How many catch basins that were inspected had a sump >50% full of trash, sediment, and debris?

0

In Year 5: Have all streets, bridges, parking lots, and right of ways been swept? (Part VI.F.3.d.i.a)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

Annually: Have all streets in business districts and commercial areas been swept? (Part VI.F.3.d.i.b)

Yes

Within five (5) years of the EDC: Have roads, bridges, parking lots, and right of way maintenance specific BMPs been implemented? (Part VI.F.3.d.ii.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

Within five (5) years of the EDC: Have winter road maintenance specific BMPs been implemented? (Part VI.F.3.d.iii.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

Please enter any comments related to the questions in this section below:

The town performs annual inspections of town facilities, in consultation with the Town Consulting Engineer as needed. Stormwater outfalls and catch basins are maintained and repaired as needed. The Town Highway Dept swept 184 miles of public streets and cleaned 1239 catch basins. Fertilizers containing phosphorus are not used on municipal properties. The town utilizes their vacuum truck to facilitate routine maintenance of stormwater management facilities and practices.

Part VIII

Does the MS4 Operator discharge to an impaired water listed in Appendix C of GP-0-24-001?

Yes

For which pollutant(s) is the waterbody impaired? Select the pollutants for all the impaired waters listed in Appendix C of GP-0-24-001 to which the MS4 Operator discharges.

Pathogens

Which requirements in this Part were completed as a coalition/group, if any?

NONE PROVIDED

Pathogens

Within three (3) years of the EDC: Has the comprehensive system mapping been updated, in a geographic information system (GIS), to include MS4 infrastructure and sewershed information for each MS4 outfall and ADA MS4 outfall discharging to a pathogens impaired water listed in Appendix C? (Part VIII.C.1.a.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 3

Within three (3) years of the EDC: Has the comprehensive system mapping been updated, in a geographic information system (GIS), to include the listed items for each MS4 outfall discharging to a pathogens impaired water listed in Appendix C? (Part VIII.C.1.b.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 3

Within three (3) years of the EDC: Has the comprehensive system mapping been updated, in a geographic information system (GIS), to include ADA MS4 outfalls discharging to a pathogens impaired water listed in Appendix C? (Part VIII.C.1.c.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 3

Minimum Control Measure 1

In Year 4 and Year 5: Have educational messages with information specific to pathogens been provided? (Part VIII.C.2.b.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 4 and 5

Minimum Control Measure 3

Within five (5) years of the EDC: Has the number of each item listed in Part VIII.C.1.b. been included on the MS4 outfall inventory for each associated MS4 outfall? (Part VIII.C.4.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Year 5

Minimum Control Measure 6

In Year 4 and Year 5: Have all streets located in sewersheds discharging to pathogens impaired segments been swept? (Part VIII.C.7.a.i.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided by Years 4 and 5

Within one (1) year of the EDC: Has the effectiveness of deterrents, population controls, and other measures that may reduce bird related pathogen contributions been evaluated? (Part VIII.C.7.b.iv.)

Yes

Within one (1) year of the EDC: Have dog waste receptacles been made available in areas where pets/domestic animals may frequent? (Part VIII.C.7.c.)

Yes

Please enter any comments related to the questions in this section below:

NONE PROVIDED

Part IX

Does the MS4 Operator discharge to a TMDL listed in Table 3 of GP-0-24-001?

Yes

To which TMDL does the MS4 Operator discharge?

New York City East of Hudson Watershed

Which requirements in this Part were completed as a coalition/group, if any?

NONE PROVIDED

New York City East of Hudson Watershed

Within three (3) years of the EDC: Has the comprehensive system mapping been updated, in a geographic information system (GIS), to include the areas with potential to contribute phosphorus to the TMDL waterbody? (Part IX.A.1.a.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Year 3

Within three (3) years of the EDC: Has the comprehensive system mapping been updated, in a geographic information system (GIS), to include the additional information for post-construction SMPs? (Part IX.A.1.b.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Year 3

Minimum Control Measure 1

Twice a year, in Year 4 and Year 5: Have educational messages with information specific to phosphorous been made available? (Part IX.A.2.b.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Years 4 and 5

Minimum Control Measure 3

Within five (5) years of the EDC: Has the number of each item listed in Part IX.A.1.a. been included on the MS4 outfall inventory for each associated MS4 outfall? (Part IX.A.4.a.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.
This information will be provided by Year 5

Once every five (5) years: Has the proper operation of on-site wastewater systems been ensured? (Part IX.A.4.b.i.)

Yes

Minimum Control Measure 4

How many high priority construction sites discharge to the TMDL?

0

Minimum Control Measure 5

Within one (1) year of the EDC: Has a retrofit plan that identifies the required components been submitted to the Department? (Part IX.A.6.f.i.a))

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

The Town is part of the EOHWC which identifies and implements stormwater retrofit projects as part of their "bubble compliance"

Within five (5) years of the EDC: Have all retrofit projects been constructed to achieve the five (5) year phosphorus reduction assigned to the MS4 Operator, as required by the Croton Watershed Phase II TMDL Implementation Plan, January 2009? (Part IX.A.6.f.i.b))

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

The Town is part of the EOHWC which identifies and implements stormwater retrofit projects as part of their "bubble compliance"

In Year 2, Year 3, Year 4, and Year 5: Have changes made to the retrofit plan including information in Part IX.A.f.i. been submitted to the Department? (Part IX.A.6.f.ii.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

The Town is part of the EOHWC which identifies and implements stormwater retrofit projects as part of their "bubble compliance"

Minimum Control Measure 6**How many catch basins are located in the TMDL watershed?**

114

Twice a year: Have all catch basins located in the TMDL watershed been inspected? (Part IX.A.7.a.)

Yes

In Year 4 and Year 5: Have all streets located in the TMDL watershed been swept? (Part IX.A.7.b.)

N/A

Please clarify the reason for selecting "No" or "N/A" for this item.

This information will be provided in Years 4 and 5

Please enter any comments related to the questions in this section below:

NONE PROVIDED

Interim Progress Status

Interim Progress Resources

Use the following webpages for more information on the permit and fact sheet:

[MS4 Permit Webpage](#)

[MS4 Toolbox](#)

Have you reviewed compliance items due within two years of EDC?

Yes

Have you reviewed compliance items due within three years of EDC?

Yes

Have you reviewed compliance items due within four years of EDC?

Yes

Have you reviewed compliance items due within five years of EDC?

Yes

Have you reviewed compliance items which need to be completed routinely (annually, every five (5) years, etc.)?

Yes

Please enter any comments related to the questions in this section.

NONE PROVIDED

Certification

The ranking elected official or Principal Executive Officer for the MS4 Operator will be signing the form.

Yes

As the Ranking Elected Official or Principal Executive Officer, please download the certification form using the link below. Complete and sign the certification. Then, upload the certification form to this Interim Progress Certification and/or Annual Report.

[Certification Form](#)

Attach completed certification form.

NONE PROVIDED

Comment

NONE PROVIDED